

SPOTID (from P3.0 if known)	Specific Improvement Type	Route	From / Cross-Street	To	County	Description	Existing Interchange/Intersection Configuration	Proposed Interchange/Intersection Configuration	Turning Movement Count Available (2013 or later)?
H111127	10 - Improve Intersection	US-501 Madison Blvd	Carver Drive		Person	Improve Intersection	At-Grade Intersection	Request the Congestion Management Team recommend an appropriate concept based on their expertise	
H111127	10 - Improve Intersection	US-501 Madison Blvd	Chubb Lake/Leasburg Road		Person	Improve Intersection	At-Grade Intersection	Request the Congestion Management Team recommend an appropriate concept based on their expertise	
H111010	10 - Improve Intersection	US-501 Madison Blvd	Johnson Street, Hurdle Mills Road, South Main Street		Person	Improve Intersection	At-Grade Intersection	Request the Congestion Management Team recommend an appropriate concept based on their expertise	
H111010	10 - Improve Intersection	US-501 Madison Blvd	Oxford Road		Person	Improve Intersection	At-Grade Intersection	Request the Congestion Management Team recommend an appropriate concept based on their expertise	
H090017	8 - Improve Interchange	I-85	US-1		Vance	Provide Additional Traffic Movements	Grade-Separation	Request the Congestion Management Team recommend an appropriate concept based on their expertise	
New Project	10 - Improve Intersection	NC-56	I-85 Ramp 191	NS Rail Crossing	Granville County	Realignment of West Lyon Station Road at NC-56 Intersection	At-Grade Intersection	Request the Congestion Management Team recommend an appropriate concept based on their expertise	

Please email this list to:  
[David Wasserman and Sarah Lee](mailto:David.Wasserman@ncdot.gov)

by **September 1, 2015**